## This Page Is Inserted by IFW Operations and is not a part of the Official Record

### **BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

### IMAGES ARE BEST AVAILABLE COPY.

As rescanning documents will not correct images, please do not report the images to the Image Problem Mailbox.

Rebecca P. Rokos
Banner & Witcoff, Ltd.
ALIGNED COMPOSITE STRUCTURES FOR
MITIGATION OF ÍMPACT DAMAGE AND RESISTANCE
TO WEAR IN DYNAMIC ENVIRONMENTS
Filed: 12/04/2001; Serial No.: 10/005,084

Page 1 of 4

1/4




FIG. 1




FIG. 2



# Rebecca P. Rokos Banner & Witcoff, Ltd. 'ALIGNED COMPOSITE STRUCTURES FOR MITIGATION OF IMPACT DAMAGE AND RESISTANCE TO WEAR IN DYNAMIC ENVIRONMENTS Filed: 12/04/2001; Serial No.: 10/005,084 Page 2 of 4

**2/4** 




FIG. 3



Rebecca P. Rokos

Banner & Witcoff, Ltd.

ALIGNED COMPOSITE STRUCTURES FOR

MITIGATION OF IMPACT DAMAGE AND RESISTANCE

TO WEAR IN DYNAMIC ENVIRONMENTS

Filed: 12/04/2001; Serial No.: 10/005,084

Page 3 of 4

## 3/4




FIG. 4




FIG. 5A




FIG. 5B




FIG. 5C



## Rebecca P. Rokos Banner & Witcoff, Ltd. ALIGNED COMPOSITE STRUCTURES FOR MITIGATION OF IMPACT DAMAGE AND RESISTANCE TO WEAR IN DYNAMIC ENVIRONMENTS Filed: 12/04/2001; Serial No.: 10/005,084 Page 4 of 4

4/4




FIG. 6




FIG. 7